


TII INDUSTRIES, INC.
1385 Akron Street, Copiague, NY 11726
Customer Service/Sales 516-789-5020

TII 98 2 2 1

COAX SERVICE MODULE
With TII In-Line™ Coax Protector
P/N 92208401 REV A
September 1997

INSTALLATION NOTE



Installing Coax Service Module Into The TII 3500 Series BNID


Locate the two mounting holes on the telco side of the NID. Position module as shown and install using screws supplied. Connect the coax ground jumper to the ground stud.

TII INDUSTRIES, INC.
1385 Akron Street, Copiague, NY 11726
Customer Service/Sales 516-789-5020

TII 98 2 2 1

COAX SERVICE MODULE
With TII In-Line™ Coax Protector
P/N 92208401 REV A
September 1997

INSTALLATION NOTE



Installing Coax Service Module Into The TII 3500 Series BNID

Locate the two mounting holes on the telco side of the NID. Position module as shown and install using screws supplied. Connect the coax ground jumper to the ground stud.